

City of Detroit
Department of Recreation Performance Audit
Exhibit 2 – O’Shea Center

Overall Evaluation – Average Condition

- Center was newly renovated with fresh paint and new equipment.
- Entrance was bright and cheerful.
- The gymnasium was small but nicely painted with a new electronic scoreboard.
- Graffiti was noted on outside restroom doors.
- Trash was scattered outside at the back of the center.



Entrance to O’Shea was bright and cheerful.

City of Detroit
Department of Recreation Performance Audit
Exhibit 2 – O’Shea Center



Nicely painted game room with new pool tables.



Big screen TV and video games in the game room.

City of Detroit
Department of Recreation Performance Audit
Exhibit 2 – O'Shea Center



Gymnasium small but nicely painted and clean.



Weight room was nicely painted and had new equipment.

City of Detroit
Department of Recreation Performance Audit
Exhibit 2 – O’Shea Center



Trash can dumped over and junk at the back of the center.



Graffiti on the outside restroom doors and debris was scattered.